

序号	报告编号	发布日期	结论	影像资料
16	GX-B1310/21-5-25009	2025. 2. 10	符合标准要求。	 A photograph showing several workers in dark clothing and hard hats working in a dimly lit tunnel or underground facility. The workers are positioned around a piece of equipment. The ceiling is supported by a metal grid structure. A yellow timestamp '2025/1/9' is visible in the bottom right corner of the image.
17	GX-B1310/21-5-25010	2025. 2. 11	符合标准要求。	 A photograph showing a worker in dark clothing and a hard hat operating a piece of equipment outdoors. The worker is wearing green gloves and is focused on the task. The equipment is blue and black. The ground is sandy or dirt-covered. A yellow timestamp '2025/1/16' is visible in the bottom right corner of the image.

18	GX-B1310/21-5-25011	2025. 2. 11	符合标准要求。	
19	GX-B1310/21-5-25012	2025. 2. 11	符合标准要求。	
20	GX-B1310/21-5-25013	2025. 2. 11	符合标准要求。	

21	GX-B1310/21-5-25014	2025. 2. 11	符合标准要求。	
22	GX-B1300/23-5-25002	2025. 2. 11	综合判定：合格。	
23	GX-B1310/21-5-25015	2025. 2. 11	符合标准要求。	

24	GX-B1300/23-5-25001	2025. 2. 11	综合判定：合格。	
25	GX-B1598/24-5-25001	2025. 2. 12	实测钢丝绳有效截面积损失百分比最大为1.80%，小于5%为正常。	