

序号	报告编号	发布日期	结论	影像资料
5	GX-B1367/22-A-23081	2023/8/4	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
6	GX-B1367/22-A-23079	2023/8/4	阻燃性不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
7	GX-B1367/22-A-23080	2023/8/4	阻燃性不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
8	GX-B1364/22-A-23629	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
9	GX-B1364/22-A-23681	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
10	GX-B1364/22-A-23628	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
11	GX-B1364/22-A-23626	2023/8/7	所检项目合格。	 <p>The photograph shows two technicians in white uniforms with '中检公信' (China Inspection and Certification) logos on their backs. They are standing in front of a large, dark industrial machine, likely a furnace or oven. The technician on the left is adjusting a control panel with several red digital displays, one of which shows '000'. The technician on the right is looking at the machine. A yellow warning triangle is visible on the machine's front panel. The date '2023/07/18' is printed in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
12	GX-B1364/22-A-23627	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
13	GX-B1364/22-A-23652	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
14	GX-B1364/22-A-23630	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
15	GX-B1364/22-A-23631	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
16	GX-B1364/22-A-23632	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
17	GX-B1364/22-A-23716	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
18	GX-B1364/22-A-23717	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
19	GX-B1364/22-A-23720	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
20	GX-B1364/22-A-23710	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
21	GX-B1364/22-A-23680	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
22	GX-B1364/22-A-23690	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
23	GX-B1364/22-A-23691	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
24	GX-B1364/22-A-23673	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
25	GX-B1364/22-A-23674	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
26	GX-B1364/22-A-23675	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
27	GX-B1364/22-A-23676	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
28	GX-B1364/22-A-23665	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
29	GX-B1364/22-A-23669	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
30	GX-B1364/22-A-23670	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
31	GX-B1364/22-A-23671	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
32	GX-B1364/22-A-23672	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
33	GX-B1364/22-A-23658	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1364/22-A-23659	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
35	GX-B1364/22-A-23660	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
36	GX-B1364/22-A-23661	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
37	GX-B1364/22-A-23663	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
38	GX-B1364/22-A-23662	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
39	GX-B1364/22-A-23711	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
40	GX-B1364/22-A-23712	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
41	GX-B1364/22-A-23713	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
42	GX-B1364/22-A-23714	2023/8/7	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
43	GX-B1364/22-A-23715	2023/8/7	所检项目合格。	