


序号	报告编号	发布日期	结论	影像资料
73	GX-B1522/20-Y-24020	2024年3月8日	所检项目合格。	
74	GX-B1495/20-Y-24225~24230	2024年3月12日	本次共检高压交流断路器6台，6台高压交流断路器所检项目合格。	

75	GX-B1547/20-Y-24072~24079	2024年3月12日	本次共检继电保护装置8台，8台继电保护装置所检项目合格。	
76	GX-B1415/22-Y-24001	2024年3月11日	综合判定：合格。	

77	GX-B1517/20-Y-24001	2024年3月12日	综合判定：合格。	
78	GX-B1328/20-Y-24028	2024年3月12日	本次共检验电器5支， 5支验电器所检项目合格。	


79	GX-B1416/22-Y-24028	2024年3月13日	综合判定：合格。	
80	GX-B1321/20-Y-24083~24090	2024年3月13日	本次共检电力电缆 8条，8条电力电缆所 检项目合格。	

81	GX-B1321/20-Y-24034~24039	2024年3月13日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	
82	GX-B1321/20-Y-24040~24045	2024年3月13日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	

83	GX-B1321/20-Y-24046~24054	2024年3月13日	本次共检验电力电缆9条，9条电力电缆所检项目合格。	
84	GX-B1321/20-Y-24055~24061	2024年3月13日	本次共检验电力电缆7条，7条电力电缆所检项目合格。	

85	GX-B1321/20-Y-24062~24065	2024年3月13日	本次共检验电力电缆4条，4条电力电缆所检项目合格。	 A photograph showing a worker in a white protective suit and helmet, kneeling on the floor of a confined space, working on a cable. The worker is wearing orange gloves. The date stamp '2024/3/12' is visible in the bottom left corner of the image.
86	GX-B1321/20-Y-24066~24071	2024年3月13日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	 A photograph showing a worker in a red protective suit working on a cable in a confined space. The worker is wearing a white helmet and is using a tool. The date stamp '2024/1/28' is visible in the bottom right corner of the image.

87	GX-B1321/20-Y-24072~24077	2024年3月13日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	
88	GX-B1321/20-Y-24078~24082	2024年3月13日	本次共检验电力电缆5条，5条电力电缆所检项目合格。	

89	GX-B1310/21-Y-24045	2024年3月14日	符合标准要求。	 A photograph showing a worker in a red protective suit and helmet, likely in a hazardous environment. The worker is wearing a red helmet with a headlamp and a red suit with reflective stripes. The worker is holding a device or tool. The background is dark, and there is a bright light source. A yellow timestamp '2024/1/28' is visible in the bottom right corner of the image.
----	---------------------	------------	---------	---