

序号	报告编号	发布日期	结论	影像资料	
221	GX-B1362/23-A-24403	2024/10/21	不合格		
222	GX-B1362/23-A-24404	2024/10/21	不合格		

序号	报告编号	发布日期	结论	影像资料	
223	GX-B1362/23-A-24405	2024/10/21	不合格		 A photograph showing two male workers in light-colored short-sleeved shirts and dark trousers working in a workshop. They are positioned next to a large, light-colored industrial machine, possibly a lathe or mill. One worker is operating the machine, while the other is observing. A date stamp '2024/10/16' is visible in the bottom right corner of the image.
224	GX-B1362/23-A-24406	2024/10/21	不合格		 A photograph showing two male workers in light-colored short-sleeved shirts and dark trousers working in a workshop. They are positioned next to a large, light-colored industrial machine, possibly a lathe or mill. One worker is operating the machine, while the other is observing. A date stamp '2024/10/16' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料	
225	GX-B1361/22-A-241092	2024/10/21	所检项目合格		
226	GX-B1361/22-A-241093	2024/10/21	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
227	GX-B1361/22-A-241094	2024/10/21	所检项目合格		
228	GX-B1361/22-A-241095	2024/10/21	合格		

序号	报告编号	发布日期	结论	影像资料	
229	GX-B1361/22-A-241096	2024/10/21	合格		
230	GX-B1361/22-A-241117	2024/10/28	合格		

序号	报告编号	发布日期	结论	影像资料	
231	GX-B1361/22-A-241119	2024/10/28	所检项目合格		 A photograph showing a male worker in a grey uniform operating a large industrial machine, possibly a press or mill, in a workshop setting. Another person is visible in the background. A yellow timestamp '2024/10/24' is in the bottom right corner.
232	GX-B1361/22-A-241120	2024/10/28	所检项目合格		 A photograph showing a male worker in a grey uniform inspecting a small part in his hands. Another person is visible in the background, working at a machine. A yellow timestamp '2024/10/24' is in the bottom right corner.

序号	报告编号	发布日期	结论	影像资料	
233	GX-B1361/22-A-241122	2024/10/28	所检项目合格		
234	GX-B1361/22-A-241123	2024/10/28	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
235	GX-B1361/22-A-241107	2024/10/29	合格		
236	GX-B1361/22-A-241108	2024/10/29	合格		

序号	报告编号	发布日期	结论	影像资料	
237	GX-B1361/22-A-241109	2024/10/29	所检项目合格		
238	GX-B1361/22-A-241097	2024/10/29	合格		

序号	报告编号	发布日期	结论	影像资料	
239	GX-B1361/22-A-241098	2024/10/29	合格		
240	GX-B1361/22-A-241099	2024/10/29	合格		

序号	报告编号	发布日期	结论	影像资料	
241	GX-B1361/22-A-241100	2024/10/29	所检项目合格		
242	GX-B1361/22-A-241101	2024/10/29	合格		

序号	报告编号	发布日期	结论	影像资料	
243	GX-B1361/22-A-241104	2024/10/29	所检项目合格		
244	GX-B1361/22-A-241105	2024/10/29	不合格		

序号	报告编号	发布日期	结论	影像资料	
245	GX-B1361/22-A-241106	2024/10/29	所检项目合格		
246	GX-B1361/22-A-241110	2024/10/29	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
247	GX-B1361/22-A-241111	2024/10/29	所检项目合格		
248	GX-B1361/22-A-241115	2024/10/29	所检项目合格		

序号	报告编号	发布日期	结论	影像资料	
249	GX-B1361/22-A-241116	2024/10/29	合格		
250	GX-B1361/22-A-241118	2024/10/29	合格		

序号	报告编号	发布日期	结论	影像资料	
251	GX-B1361/22-A-241121	2024/10/29	不合格		