

序号	报告编号	发布日期	结论	影像资料
67	GX-B1310/21-2-24441	2025/1/17	符合标准要求。	 A photograph showing a worker in a blue uniform and red helmet standing at night next to a piece of equipment. The equipment has a sign with the Chinese character '安' (An) on it. The date '2021/11/29' is visible in the bottom right corner of the image.
68	GX-B1310/21-2-24442	2025/1/14	符合标准要求。	 A photograph showing a worker in a blue uniform and red helmet working in a dark tunnel or underground setting. The worker is holding a flashlight. The date '2021/12/30' is visible in the bottom right corner of the image.
69	GX-B1310/21-2-24443	2025/1/14	符合标准要求。	 A photograph showing a worker in a blue uniform and red helmet working in a dark tunnel or underground setting. The worker is holding a flashlight. The date '2024/12/30' is visible in the bottom right corner of the image.

70	GX-B1310/21-2-24444	2025/1/14	符合标准要求。	 <p>2024/12/30</p>
71	GX-B1515/22-2-24022	2025/1/14	所检项目合格	 <p>2024/12/29</p>
72	GX-B1612/23-2-24019	2025/1/18	所检项目合格	 <p>2024/12/09</p>

73	GX-B1612/23-2-24020	2025/1/18	所检项目合格	 <p>2024/12/09</p>
74	GX-B1612/23-2-24021	2025/1/18	所检项目合格	 <p>2024/12/09</p>
75	GX-B1612/23-2-24022	2025/1/18	所检项目合格	 <p>2024/12/09</p>

76	GX-B1612/23-2-24023	2025/1/18	所检项目合格	 2024/12/09	
77	GX-B1612/23-2-24024	2025/1/18	所检项目合格	 2024/12/09	
78	GX-B1612/23-2-24025	2025/1/18	所检项目合格	 2024/12/09	

79	GX-B1612/23-2-24026	2025/1/18	所检项目合格		
80	GX-B1612/23-2-24027	2025/1/18	所检项目合格		
81	GX-B1612/23-2-24028	2025/1/18	所检项目合格		

82	GX-B1612/23-2-24029	2025/1/18	所检项目合格	 2024/12/10	
83	GX-B1612/23-2-24030	2025/1/18	所检项目合格	 2024/12/10	
84	GX-B1612/23-2-24031	2025/1/18	所检项目合格	 2024/12/10	

85	GX-B1612/23-2-24032	2025/1/18	所检项目合格	 <p>2024/12/10</p>
86	GX-B1612/23-2-24033	2025/1/18	所检项目合格	 <p>2024/12/10</p>
87	GX-B1612/23-2-24034	2025/1/18	所检项目合格	 <p>2024/12/10</p>

88	GX-B1612/23-2-24035	2025/1/18	所检项目合格		
89	GX-B1612/23-2-24036	2025/1/18	所检项目合格		
90	GX-B1612/23-2-24037	2025/1/18	所检项目合格		

91	GX-B1612/23-2-24038	2025/1/18	所检项目合格	 <p>2024/12/11</p>
92	GX-B1612/23-2-24039	2025/1/18	所检项目合格	 <p>2024/12/11</p>
93	GX-B1612/23-2-24040	2025/1/18	所检项目合格	 <p>2024/12/11</p>

94	GX-B1612/23-2-24041	2025/1/18	所检项目合格	 2024/12/11	
95	GX-B1612/23-2-24042	2025/1/18	所检项目合格	 2024/12/11	
96	GX-B1612/23-2-24043	2025/1/18	所检项目合格	 2024/12/11	

97	GX-B1612/23-2-24046	2025/1/18	所检项目合格	 <p>2024/12/12</p>
98	GX-B1612/23-2-24047	2025/1/18	所检项目合格	 <p>2024/12/12</p>
99	GX-B1612/23-2-24048	2025/1/21	所检项目合格	 <p>2024/12/10</p>

100	GX-B1612/23-2-24049	2025/1/21	所检项目合格	 <p>2024/12/12</p>	
101	GX-B1612/23-2-24050	2025/1/21	所检项目合格	 <p>2024/12/12</p>	
102	GX-B1612/23-2-24051	2025/1/18	所检项目合格	 <p>2024/12/15</p>	

103	GX-B1612/23-2-24052	2025/1/21	所检项目合格	 <p>2024/12/15</p>	
104	GX-B1612/23-2-24053	2025/1/21	所检项目合格	 <p>2024/12/11</p>	
105	GX-B1612/23-2-24054	2025/1/18	所检项目合格	 <p>2024/12/12</p>	

106	GX-B1612/23-2-24055	2025/1/18	所检项目合格	 <p>2024/12/13</p>
107	GX-B1612/23-2-24056	2025/1/18	所检项目合格	 <p>2024/12/13</p>
108	GX-B1612/23-2-24057	2025/1/18	所检项目合格	 <p>2024/12/13</p>


109	GX-B1612/23-2-24058	2025/1/18	所检项目合格	 <p>2024/12/13</p>	
110	GX-B1612/23-2-24059	2025/1/18	所检项目合格	 <p>2024/12/13</p>	
111	GX-B1612/23-2-24060	2025/1/18	所检项目合格	 <p>2024/12/13</p>	


112	GX-B1612/23-2-24061	2025/1/18	所检项目合格	 <p>2024/12/13</p>	
113	GX-B1612/23-2-24062	2025/1/18	所检项目合格	 <p>2024/12/13</p>	
114	GX-B1612/23-2-24063	2025/1/18	所检项目合格	 <p>2024/12/13</p>	

115	GX-B1612/23-2-24064	2025/1/21	所检项目合格	 <p>2024/12/15</p>
116	GX-B1612/23-2-24065	2025/1/21	所检项目合格	 <p>2024/12/14</p>
117	GX-B1612/23-2-24066	2025/1/21	所检项目合格	 <p>2024/12/14</p>

118	GX-B1612/23-2-24067	2025/1/21	所检项目合格	 <p>2024/12/14</p>	
119	GX-B1612/23-2-24068	2025/1/21	所检项目合格	 <p>2024/12/14</p>	
120	GX-B1612/23-2-24069	2025/1/21	所检项目合格	 <p>2024/12/14</p>	

121	GX-B1612/23-2-24070	2025/1/18	所检项目合格		
122	GX-B1612/23-2-24071	2025/1/21	所检项目合格		
123	GX-B1612/23-2-24072	2025/1/21	所检项目合格		

124	GX-B1612/23-2-24073	2025/1/21	所检项目合格	
125	GX-B1612/23-2-24074	2025/1/21	所检项目合格	
126	GX-B1328/20-2-24130	2025. 1. 20	所检项目合格	

127	GX-B1328/20-2-24131	2025. 1. 20	所检项目合格	 2024/12/18
128	GX-B1598/24-2-24361	2025. 1. 18	实测钢丝绳有效截面积损失百分比最大为2.87%，小于5%为正常。 。	 2024/12/10
129	GX-B1598/24-2-24362	2025. 1. 18	实测钢丝绳有效截面积损失百分比最大为0.85%，小于5%为正常。 。	 2024/12/11

130	GX-B1598/24-2-24363	2025. 1. 18	实测钢丝绳有效截面积损失百分比最大为1.83%，小于5%为正常。 。		
131	GX-B1598/24-2-24364	2025. 1. 18	实测钢丝绳有效截面积损失百分比最大为3.84%，小于5%为正常。 。		
132	GX-B1598/24-2-24365	2025. 1. 18	实测钢丝绳有效截面积损失百分比最大为2.59%，小于5%为正常。 。		

133	GX-B1598/24-2-24327	2025. 1. 17	实测钢丝绳有效截面积 损失百分比最大为 0.85%，小于5%为正常。	
134	GX-B1598/24-2-24328	2025. 1. 17	实测钢丝绳有效截面积 损失百分比最大为 0.82%，小于5%为正常。	
135	GX-B1598/24-2-24329	2025. 1. 17	实测钢丝绳有效截面积 损失百分比最大为 0.71%，小于5%为正常。	

136	GX-B1598/24-2-24330	2025. 1. 17	实测钢丝绳有效截面积 损失百分比最大为 0.96%，小于5%为正常。	 <p>2024/12/08</p>
137	GX-B1612/23-2-24019	2025/1/18	所检项目合格	 <p>2024/12/09</p>
138	GX-B1612/23-2-24020	2025/1/18	所检项目合格	 <p>2024/12/09</p>

139	GX-B1612/23-2-24021	2025/1/18	所检项目合格	 <p>2024/12/09</p>
140	GX-B1612/23-2-24022	2025/1/18	所检项目合格	 <p>2024/12/09</p>
141	GX-B1612/23-2-24023	2025/1/18	所检项目合格	 <p>2024/12/09</p>

142	GX-B1612/23-2-24024	2025/1/18	所检项目合格	 <p>2024/12/09</p>	
143	GX-B1612/23-2-24025	2025/1/18	所检项目合格	 <p>2024/12/09</p>	
144	GX-B1612/23-2-24026	2025/1/18	所检项目合格	 <p>2024/12/09</p>	

145	GX-B1612/23-2-24027	2025/1/18	所检项目合格	 <p>2024/12/09</p>	
146	GX-B1612/23-2-24028	2025/1/18	所检项目合格	 <p>2024/12/09</p>	
147	GX-B1612/23-2-24029	2025/1/18	所检项目合格	 <p>2024/12/10</p>	

148	GX-B1612/23-2-24030	2025/1/18	所检项目合格	 2024/12/10
149	GX-B1612/23-2-24031	2025/1/18	所检项目合格	 2024/12/10
150	GX-B1612/23-2-24032	2025/1/18	所检项目合格	 2024/12/10

151	GX-B1612/23-2-24033	2025/1/18	所检项目合格	
152	GX-B1612/23-2-24034	2025/1/18	所检项目合格	
153	GX-B1612/23-2-24035	2025/1/18	所检项目合格	

154	GX-B1612/23-2-24036	2025/1/18	所检项目合格	 <p>2024/12/11</p>
155	GX-B1612/23-2-24037	2025/1/18	所检项目合格	 <p>2024/12/11</p>
156	GX-B1612/23-2-24038	2025/1/18	所检项目合格	 <p>2024/12/11</p>

157	GX-B1612/23-2-24039	2025/1/18	所检项目合格		
158	GX-B1612/23-2-24040	2025/1/18	所检项目合格		
159	GX-B1612/23-2-24041	2025/1/18	所检项目合格		

160	GX-B1612/23-2-24042	2025/1/18	所检项目合格	 <p>2024/12/11</p>	
161	GX-B1612/23-2-24043	2025/1/18	所检项目合格	 <p>2024/12/11</p>	
162	GX-B1612/23-2-24046	2025/1/18	所检项目合格	 <p>2024/12/12</p>	

163	GX-B1612/23-2-24047	2025/1/18	所检项目合格	 <p>2024/12/12</p>
164	GX-B1612/23-2-24048	2025/1/21	所检项目合格	 <p>2024/12/10</p>
165	GX-B1612/23-2-24049	2025/1/21	所检项目合格	 <p>2024/12/12</p>

166	GX-B1612/23-2-24050	2025/1/21	所检项目合格	 A photograph of an inspector in a grey jacket and red cap standing in front of a yellow truck. The truck has a blue license plate with the number 桂A5021. The date 2024/12/12 is visible in the bottom right corner of the photo.
167	GX-B1612/23-2-24051	2025/1/18	所检项目合格	 A photograph of an inspector in a grey jacket standing in front of a red truck. The truck has a blue license plate with the number 桂A5021. The date 2024/12/18 is visible in the bottom right corner of the photo.
168	GX-B1612/23-2-24052	2025/1/21	所检项目合格	 A photograph of an inspector in a grey jacket standing in front of a dark-colored truck at night. The truck has a blue license plate with the number 桂A5021. The date 2024/12/15 is visible in the bottom right corner of the photo.

169	GX-B1612/23-2-24053	2025/1/21	所检项目合格	 <p>2024/12/11</p>
170	GX-B1612/23-2-24054	2025/1/18	所检项目合格	 <p>2024/12/18</p>
171	GX-B1612/23-2-24055	2025/1/18	所检项目合格	 <p>2024/12/18</p>

172	GX-B1612/23-2-24056	2025/1/18	所检项目合格	 <p>2024/12/13</p>
173	GX-B1612/23-2-24057	2025/1/18	所检项目合格	 <p>2024/12/13</p>
174	GX-B1612/23-2-24058	2025/1/18	所检项目合格	 <p>2024/12/13</p>

175	GX-B1612/23-2-24059	2025/1/18	所检项目合格	
176	GX-B1612/23-2-24060	2025/1/18	所检项目合格	
177	GX-B1612/23-2-24061	2025/1/18	所检项目合格	

178	GX-B1612/23-2-24062	2025/1/18	所检项目合格	 <p>2024/12/13</p>	
179	GX-B1612/23-2-24063	2025/1/18	所检项目合格	 <p>2024/12/13</p>	
180	GX-B1612/23-2-24064	2025/1/21	所检项目合格	 <p>2024/12/15</p>	

181	GX-B1612/23-2-24065	2025/1/21	所检项目合格	 <p>2024/12/14</p>
182	GX-B1612/23-2-24066	2025/1/21	所检项目合格	 <p>2024/12/14</p>
183	GX-B1612/23-2-24067	2025/1/21	所检项目合格	 <p>2024/12/14</p>

184	GX-B1612/23-2-24068	2025/1/21	所检项目合格		
185	GX-B1612/23-2-24069	2025/1/21	所检项目合格		
186	GX-B1612/23-2-24070	2025/1/18	所检项目合格		

187	GX-B1612/23-2-24071	2025/1/21	所检项目合格	 <p>2024/12/14</p>	
188	GX-B1612/23-2-24072	2025/1/21	所检项目合格	 <p>2024/12/15</p>	
189	GX-B1612/23-2-24073	2025/1/21	所检项目合格	 <p>2024/12/15</p>	

190	GX-B1612/23-2-24074	2025/1/21	所检项目合格		 <p>2024/12/15</p>
191	GX-B1323/21-2-25008~25011	2025/1/22	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。		 <p>2025/01/09</p>
192	GX-B1495/20-2-25001~25003	2025. 1. 22	本次共检防爆型高压配电装置3台，3台所检项目合格。		 <p>2025/01/08</p>

193	GX-B1495/20-2-25004~25005	2025. 1. 22	本次共检高压开关柜2台，2台所检项目合格。			
194	GX-B1495/20-2-25014~25019	2025. 1. 22	本次共检防爆型高压配电装置6台，6台所检项目合格。			
195	GX-B1495/20-2-25020~25027	2025. 1. 22	本次共检防爆型高压配电装置8台，8台所检项目合格。			

196	GX-B1495/20-2-25030~25043	2025. 1. 22	本次共检防爆型高压配电装置14台，14台所检项目合格。			
197	GX-B1495/20-2-25044~25061	2025. 1. 22	本次共检高压开关柜18台，18台所检项目合格。			
198	GX-B1329/21-2-25024~25025	2025. 1. 21	本次共检氧化锌避雷器2组，2组所检项目合格。			

199	GX-B1312/20-2-25007	2025. 1. 21	所检项目合格。		
200	GX-B1312/20-2-25008~25010	2025. 1. 21	本次共检电力变压器 3台，3台电力变压器所 检项目合格。		
201	GX-B1312/20-2-25011~25014	2025. 1. 21	本次共检电力变压器 4台，4台所检项目合格 。		

202	GX-B1314/21-2-25001~25003	2025. 1. 21	本次共检干式电抗器 3台，3台所检项目合格。 。	 2025/01/08
203	GX-B1314/21-2-25004~25007	2025. 1. 21	本次共检干式电抗器 4台，4台所检项目合格。 。	 2025/01/10
204	GX-B1323/21-2-25001~25003	2025. 1. 21	本次共检三相交流电动机 3台，3台三相交流电动机所检项目合格。	 2025/01/08

205	GX-B1323/21-2-25004~25007	2025. 1. 21	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。			
206	GX-B1301/23-2-25004	2025. 1. 22	综合判定：不合格。			
207	GX-B1536/20-2-25001	2025. 1. 21	综合判定：合格。			

208	GX-B1515/22-2-25001	2025. 1. 21	滚筒绳衬直径与钢丝绳直径之比小于50倍。 除上述问题外，其余所检项目合格。	
209	GX-B1495/20-3-25076~25089	2025. 1. 20	所检项目合格。	
210	GX-B1495/20-3-25090~25093	2025. 1. 20	所检项目合格。	


211	GX-B1495/20-3-25101~25110	2025. 1. 20	所检项目合格。		
212	GX-B1495/20-3-25111~25117	2025. 1. 20	所检项目合格。		
213	GX-B1312/20-2-25001~25002	2025. 1. 22	所检项目合格。		

214	GX-B1312/20-2-25003~25004	2025. 1. 22	所检项目合格。	
215	GX-B1312/20-2-25005~25006	2025. 1. 22	所检项目合格。	
216	GX-B1312/20-2-25015~25016	2025. 1. 22	所检项目合格。	

217	GX-B1321/20-2-25034~25037	2025. 1. 22	所检项目合格。	
218	GX-B1321/20-2-25038~25039	2025. 1. 22	所检项目合格。	
219	GX-B1321/20-2-25045~25048	2025/1/22	本次共检电力电缆 4条，4条电力电缆所 检项目合格。	

220	GX-B1321/20-2-25040~25044	2025/1/22	本次共检电力电缆5条，5条电力电缆所检项目合格。	
221	GX-B1321/20-2-25049~25052	2025/1/22	本次共检电力电缆4条，4条电力电缆所检项目合格。	
222	GX-B1321/20-2-25055~25062	2025/1/22	本次共检电力电缆8条，8条电力电缆所检项目合格。	

223	GX-B1312/20-2-25017~25021	2025/1/22	本次共检电力变压器5台，5台电力变压器所检项目合格。		 <p>2025/01/11</p>
224	GX-B1312/20-2-25022~25024	2025/1/22	本次共检电力变压器3台，3台电力变压器所检项目合格。		 <p>2025/01/09</p>
225	GX-B1312/20-2-25025~25027	2025/1/22	本次共检电力变压器3台，3台电力变压器所检项目合格。		 <p>2025/01/10</p>

226	GX-B1321/20-2-25053~25054	2025. 1. 22	所检项目合格	
227	GX-B1321/20-2-25063~25068	2025. 1. 22	所检项目合格	
228	GX-B1611/23-2-24015	2025. 1. 23	所检项目合格。	

229	GX-B1611/23-2-24016	2025. 1. 23	所检项目合格。	
230	GX-B1611/23-2-24017	2025. 1. 23	所检项目合格。	
231	GX-B1611/23-2-24018	2025. 1. 23	所检项目合格。	

232	GX-B1611/23-2-24019	2025. 1. 23	所检项目合格。	 <p>2024/12/09</p>
233	GX-B1611/23-2-24020	2025. 1. 23	所检项目合格。	 <p>2024/12/09</p>
234	GX-B1611/23-2-24021	2025. 1. 23	所检项目合格。	 <p>2024/12/10</p>

235	GX-B1611/23-2-24022	2025. 1. 23	所检项目合格。	 <p>A man wearing a grey jacket and dark pants stands next to a yellow truck. The truck has a circular logo on its side. The date '2024/12/10' is visible in the bottom right corner of the photo.</p>
236	GX-B1611/23-2-24023	2025. 1. 23	所检项目合格。	 <p>A man wearing a grey jacket, dark pants, and a red hard hat stands next to a yellow truck. The truck has a circular logo on its side. The date '2024/12/10' is visible in the bottom right corner of the photo.</p>
237	GX-B1611/23-2-24024	2025. 1. 23	所检项目合格。	 <p>A man wearing a grey jacket, dark pants, and a red hard hat stands in front of a yellow truck. The truck has a circular logo on its side. The date '2024/12/10' is visible in the bottom right corner of the photo.</p>

238	GX-B1611/23-2-24025	2025. 1. 23	所检项目合格。	 <p>2024/12/14</p>
239	GX-B1611/23-2-24026	2025. 1. 23	所检项目合格。	 <p>2024/12/14</p>
240	GX-B1611/23-2-24027	2025. 1. 23	所检项目合格。	 <p>2024/12/14</p>

241	GX-B1611/23-2-24028	2025. 1. 23	所检项目合格。	
242	GX-B1611/23-2-24029	2025. 1. 23	所检项目合格。	
243	GX-B1611/23-2-24030	2025. 1. 23	所检项目合格。	

244	GX-B1611/23-2-24031	2025. 1. 23	所检项目合格。	 2024/12/12
245	GX-B1611/23-2-24032	2025. 1. 23	所检项目合格。	 2024/12/15
246	GX-B1611/23-2-24033	2025. 1. 23	所检项目合格。	 2024/12/12

247	GX-B1611/23-2-24034	2025. 1. 23	所检项目合格。	
248	GX-B1611/23-2-24035	2025. 1. 23	所检项目合格。	
249	GX-B1301/23-2-25001	2025. 1. 23	综合判定：合格。	

250	GX-B1301/23-2-25005	2025/1/23	综合判定：合格。	 <p>2025-01-16</p>
251	GX-B1301/23-2-25002	2025. 1. 23	综合判定：合格。	 <p>2025-01-15</p>

252	GX-B1312/20-2-25028~25029	2025/1/23	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>2025/01/11</p>
253	GX-B1310/21-2-24421	2025. 1. 23	符合标准要求。	 <p>2024/12/01</p>

254	GX-B1310/21-2-24422	2025. 1. 23	符合标准要求。	
255	GX-B1310/21-2-24423	2025. 1. 23	符合标准要求。	

256	GX-B1310/21-2-24424	2025. 1. 23	符合标准要求。	
257	GX-B1310/21-2-24425	2025. 1. 23	符合标准要求。	

258	GX-B1310/21-2-24426	2025. 1. 23	符合标准要求。	 <p>2024/12/01</p>
259	GX-B1310/21-2-24427	2025. 1. 23	符合标准要求。	 <p>2024/12/01</p>

260	GX-B1310/21-2-24428	2025. 1. 23	符合标准要求。	
261	GX-B1310/21-2-24429	2025. 1. 23	符合标准要求。	

262	GX-B1310/21-2-24430	2025. 1. 23	符合标准要求。	 <p>2024/12/01</p>
263	GX-B1321/20-2-25001~25009	2025. 1. 24	本次共检电力电缆9条， 9条电力电缆所检项目合格。	 <p>2025-01-04</p>

264	GX-B1321/20-2-25010~25016	2025. 1. 24	本次共检电力电缆7条，7条电力电缆所检项目合格。	
265	GX-B1321/20-2-25017~25026	2025. 1. 24	本次共检电力电缆10条，10条电力电缆所检项目合格。	

266	GX-B1321/20-2-25027~25033	2025. 1. 24	本次共检电力电缆7条， 7条电力电缆所检项目合格。	
267	GX-B1301/23-2-25003	2025. 1. 24	综合判定:合格。	

268	GX-B1310/21-2-25010	2025. 1. 24	符合标准要求。	 <p>A worker wearing a red hard hat and a blue jacket is inspecting a large, dark-colored industrial component, possibly a turbine or pump housing. The worker is holding a tool or device. The date '2025/01/09' is visible in the bottom right corner of the image.</p>
269	GX-B1428/21-2-25010	2025. 1. 24	无缺陷迹痕显示。	 <p>A worker wearing a red hard hat and a blue jacket is inspecting a large, blue industrial component, possibly a turbine or pump housing. The worker is holding a tool or device. The date '2025/01/09' is visible in the bottom right corner of the image.</p>

270	GX-B1310/21-2-25011	2025. 1. 24	符合标准要求。	 <p>2025/01/10</p>
271	GX-B1428/21-2-25011	2025. 1. 24	无缺陷迹痕显示。	 <p>2025/01/10</p>

272	GX-B1495/20-2-25006~25013	2025. 1. 24	所检项目合格	
273	GX-B1495/20-2-25062~25063	2025. 1. 24	所检项目合格	

274	GX-B1495/20-2-25064~25067	2025. 1. 24	所检项目合格	 <p>A worker wearing a red hard hat and a grey jacket is operating a red industrial machine. The machine has a yellow railing in front of it. The date 2025/1/09 is visible in the bottom right corner of the photo.</p>
275	GX-B1495/20-2-25072~25077	2025. 1. 24	所检项目合格	 <p>A worker wearing a red hard hat and a blue uniform is standing next to a red industrial machine. The machine has a yellow railing in front of it. The date 2025/01/10 is visible in the bottom right corner of the photo.</p>

276	GX-B1495/20-2-25068~25071	2025. 1. 24	所检项目合格	
277	GX-B1495/20-2-25078~25084	2025. 1. 24	所检项目合格	

278	GX-B1329/21-2-25022~25023	2025. 1. 24	所检项目合格	 <p>2025/01/09</p>
279	GX-B1329/21-2-25001~25021	2025. 1. 25	所检项目合格	 <p>2025/01/09</p>