

序号	报告编号	发布日期	结论	影像资料
296	GX-B1363/22-A-25026	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
297	GX-B1458/22-A-25001	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
298	GX-B1458/22-A-25002	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
299	GX-B1367/22-A-25006	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
300	GX-B1458/22-A-25007	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
301	GX-B1458/22-A-25008	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
302	GX-B1458/22-A-25009	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
303	GX-B1458/22-A-25010	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
304	GX-B1367/22-A-25013	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
305	GX-B1367/22-A-25016	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
306	GX-B1363/22-A-25031	2025/1/24	所检项目合格。	 A photograph showing two workers in dark jackets and safety glasses inspecting a large, complex industrial machine. The machine has a prominent vertical pipe and a large cylindrical component. The workers are positioned on either side of the machine, looking at it intently. The background shows a factory interior with windows and a white wall. A date stamp '2025.01.' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
307	GX-B1363/22-A-25027	2025/1/24	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
308	GX-B1363/22-A-25032	2025/1/24	所检项目合格。	 A photograph showing two workers in winter clothing and yellow gloves inspecting a large, complex industrial machine. The machine has a prominent yellow triangular warning sign on its side. The workers are positioned on either side of the machine, looking into its open compartments. The background shows an indoor industrial setting with a window and a white wall. A date stamp '2025.01.' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
309	GX-B1363/22-A-25041	2025/1/24	所检项目合格。	 A photograph showing two workers in blue jackets and yellow gloves inspecting a large, rusted industrial furnace or boiler. The furnace has a large cylindrical chimney on top. The workers are looking into the open doors of the furnace. A date stamp '2025.01.' is visible in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
310	GX-B1363/22-A-25042	2025/1/24	所检项目合格。	