

序号	报告编号	发布日期	结论	影像资料
17	GX-B1312/20-7-25006~25008	2025/2/18	本次共检电力变压器3台，3台电力变压器所检项目合格。	 <p>A photograph showing three workers in a tunnel. They are wearing hard hats and safety gear. One worker is holding a clipboard and looking at it, while the others are looking towards the camera. The tunnel is dimly lit with blue lights. A yellow timestamp '2025. 1. 19' is visible in the bottom right corner of the photo.</p>
18	GX-B1312/20-7-25014~25017	2025/2/18	本次共检电力变压器4台，4台电力变压器所检项目合格。	 <p>A photograph of a worker in a tunnel. The worker is wearing a white protective suit and a hard hat. The worker is standing in a dark tunnel with some equipment visible in the background. A yellow timestamp '2025. 1. 20' is visible in the bottom right corner of the photo.</p>

19	GX-B1321/20-7-25034~25044	2025/2/18	电缆11条，11条电力电缆	 <p>2025. 1. 19</p>
20	GX-B1321/20-7-25045~25053	2025/2/18	电缆9条，9条电力电缆	 <p>2025. 1. 20</p>
21	GX-B1495/20-7-25001~25012	2025/2/18	本次共检高压防爆开关12台，12台高压防爆开关所检项目合格。	 <p>2025. 1. 19</p>

22	GX-B1495/20-7-25033~25041	2025/2/18	本次共检高压防爆开关 9台，9台高压防爆开关 所检项目合格。	
23	GX-B1559/22-7-25002	2025. 2. 20	所检项目合格。	