

序号	报告编号	发布日期	结论	影像资料
111	GX-B1322/21-Y-25001	2025. 4. 15	所检项目合格	
112	GX-B1322/21-Y-25002	2025. 4. 15	所检项目合格	
113	GX-B1322/21-Y-25003	2025. 4. 15	所检项目合格	

114	GX-B1322/21-Y-25004	2025. 4. 15	所检项目合格	 2025.3.24
115	GX-B1305/21-Y-25002	2025. 4. 15	综合判定：合格。	 2025/3/26
116	GX-B1423/20-Y-25013	2025年4月15日	综合判定：合格	 2025/4/9

117	GX-B1423/20-Y-25014	2025年4月15日	综合判定：合格	
118	GX-B1312/20-Y-25056~25059	2025年4月15日	本次共检煤矿用变压器4台，4台煤矿用变压器所检项目合格。	
119	GX-B1312/20-Y-25060~25061	2025年4月15日	本次共检煤矿用防爆干式变压器2台，2台煤矿用防爆干式变压器所检项目合格。	

120	GX-B1312/20-Y-25062~25063	2025年4月15日	本次共检电力变压器2台，2台电力变压器所检项目合格。	
121	GX-B1312/20-Y-25064~25075	2025年4月15日	本次共检煤矿用防爆干式变压器12台，12台煤矿用防爆干式变压器所检项目合格。	
122	GX-B1539/22-Y-25037	2025年4月16日	所检项目合格。	

123	GX-B1521/20-Y-25007	2025年4月16日	所检项目合格。	
124	GX-B1305/21-Y-25003	2025. 4. 18	综合判定：合格。	
125	GX-B1305/21-Y-25004	2025. 4. 18	综合判定：合格。	

126	GX-B1305/21-Y-25005	2025. 4. 18	综合判定：合格。	
127	GX-B1305/21-Y-25006	2025. 4. 18	综合判定：合格。	
128	GX-B1385/21-Y-25013	2025年4月17日	所检项目合格。	

129	GX-B1385/21-Y-25014	2025年4月17日	所检项目合格。	 
130	GX-B1385/21-Y-25015	2025年4月17日	所检项目合格。	
131	GX-B1385/21-Y-25016	2025年4月17日	所检项目合格。	

132	GX-B1385/21-Y-25017	2025年4月17日	所检项目合格。	
133	GX-B1385/21-Y-25018	2025年4月17日	所检项目合格。	
134	GX-B1385/21-Y-25019	2025年4月17日	所检项目合格。	

135	GX-B1385/21-Y-25020	2025年4月17日	所检项目合格。	
136	GX-B1385/21-Y-25021	2025年4月17日	所检项目合格。	
137	GX-B1385/21-Y-25022	2025年4月17日	所检项目合格。	

138	GX-B1380/20-Y-25003	2025年4月17日	所检项目合格。	 A worker in a grey uniform and red helmet is inspecting a large industrial metal structure. The worker is holding a tool and looking at the structure. The date 2025.3.24 is visible in the bottom right corner of the image.
139	GX-B1380/20-Y-25004	2025年4月17日	所检项目合格。	 A worker in a grey uniform and red helmet is inspecting a large industrial metal structure. The worker is holding a tool and looking at the structure. The date 2025.3.24 is visible in the bottom right corner of the image.
140	GX-B1380/20-Y-25005	2025年4月17日	所检项目合格。	 A worker in a blue uniform and red helmet is inspecting a large industrial metal structure. The worker is holding a tool and looking at the structure. The date 2025.3.28 is visible in the bottom right corner of the image.

141	GX-B1382/21-Y-25003	2025年4月17日	综合判定:合格。	 A worker in a red hard hat and blue uniform is standing on a yellow safety platform or scaffolding inside a large industrial building with a high ceiling and steel beams. A yellow timestamp '2025-3-28' is visible in the bottom right corner of the photo.
142	GX-B1382/21-Y-25004	2025年4月17日	综合判定:合格。	 A worker in a red hard hat and blue uniform is standing on a high yellow safety platform or scaffolding inside a large industrial building with a high ceiling and steel beams. A yellow timestamp '2025-3-28' is visible in the bottom right corner of the photo.
143	GX-B1382/21-Y-25005	2025年4月17日	综合判定:合格。	 A worker in a red hard hat and blue uniform is standing on a yellow safety platform or scaffolding inside a large industrial building with a high ceiling and steel beams. A yellow timestamp '2025-3-28' is visible in the bottom right corner of the photo.


144	GX-B1308/21-Y-25003	2025年4月16日	所检项目合格。	
145	GX-B1310/21-Y-25039	2025. 4. 16	符合标准要求。	
146	GX-B1310/21-Y-25040	2025. 4. 16	符合标准要求。	

147	GX-B1310/21-Y-25041	2025. 4. 16	符合标准要求。	
148	GX-B1427/21-Y-25042	2025. 4. 16	无缺陷磁痕显示。	
149	GX-B1310/21-Y-25043	2025. 4. 16	符合标准要求。	

150	GX-B1310/21-Y-25044	2025. 4. 16	符合标准要求。	
151	GX-B1310/21-Y-25045	2025. 4. 16	符合标准要求。	
152	GX-B1427/21-Y-25046	2025. 4. 16	无缺陷磁痕显示。	

153	GX-B1310/21-Y-25047	2025. 4. 16	符合标准要求。	
154	GX-B1310/21-Y-25048	2025. 4. 16	符合标准要求。	
155	GX-B1310/21-Y-25049	2025. 4. 16	符合标准要求。	

156	GX-B1427/21-Y-25050	2025. 4. 16	无缺陷磁痕显示。	
157	GX-B1310/21-Y-25051	2025. 4. 16	符合标准要求。	
158	GX-B1310/21-Y-25052	2025. 4. 16	符合标准要求。	

159	GX-B1310/21-Y-25053	2025. 4. 16	符合标准要求。	
160	GX-B1427/21-Y-25054	2025. 4. 16	无缺陷磁痕显示。	
161	GX-B1310/21-Y-25055	2025. 4. 16	符合标准要求。	

162	GX-B1310/21-Y-25056	2025. 4. 16	符合标准要求。	
163	GX-B1310/21-Y-25057	2025. 4. 16	符合标准要求。	
164	GX-B1427/21-Y-25058	2025. 4. 16	无缺陷磁痕显示。	

165	GX-B1310/21-Y-25059	2025. 4. 16	符合标准要求。	
166	GX-B1310/21-Y-25060	2025. 4. 16	符合标准要求。	
167	GX-B1310/21-Y-25061	2025. 4. 16	符合标准要求。	

168	GX-B1427/21-Y-25062	2025. 4. 16	无缺陷磁痕显示。	 A worker in a red helmet and safety gear is performing a magnetic particle inspection on a vertical metal component. The worker is using a handheld device to apply or observe the magnetic field. The background shows industrial equipment. 2025.3.27
169	GX-B1310/21-Y-25063	2025. 4. 16	符合标准要求。	 A worker in a yellow helmet and safety gear is performing a magnetic particle inspection on a large, curved metal component. The worker is using a handheld device to apply or observe the magnetic field. The background shows industrial equipment. 2025.3.28
170	GX-B1310/21-Y-25064	2025. 4. 16	符合标准要求。	 A worker in a red helmet and safety gear is performing a magnetic particle inspection on a large, curved metal component. The worker is using a handheld device to apply or observe the magnetic field. The background shows industrial equipment. 2025.3.28

171	GX-B1310/21-Y-25065	2025. 4. 16	符合标准要求。	
172	GX-B1427/21-Y-25066	2025. 4. 16	无缺陷磁痕显示。	