



序号	报告编号	发布日期	结论	影像资料
43	GX-B1310/21-7-25161	2025/9/8	符合标准要求。	 A worker wearing a red hard hat, safety glasses, and a grey work jacket with a safety harness is kneeling and working on a large, dark industrial machine. The machine has a vertical component with a textured surface. The date '2025/8/13' is visible in the bottom right corner of the photo.
44	GX-B1328/25-7-25108	2025.9.10	本次共检绝缘手套236只，236只绝缘手套合格。	 Two workers in red hard hats are in a large industrial space. One worker is kneeling and inspecting a large number of electrical insulating gloves (rubber boots) that are laid out on the floor. There are several buckets and containers around the gloves. The date '2025/9/7' is visible in the bottom right corner of the photo.

45	GX-B1328/25-7-25109	2025.9.10	本次共检绝缘靴 154只，154只绝缘靴合格。	
46	GX-B1328/25-7-25110	2025.9.10	本次共检便携式短路 接地线36套，36套携带 式短路接地线合格。	

47	GX-B1328/25-7-25111	2025. 9. 10	本次共检验电器 58支，58支验电器合格 。	
----	---------------------	-------------	------------------------------	---