

序号	报告编号	发布日期	结论	影像资料
25	GX-B1523/20-Y-25001	2025. 9. 24	所检项目合格	 A photograph showing a worker in a red helmet and blue uniform operating a blue industrial machine in a dark tunnel. The machine has a digital display and various controls. The worker is standing next to the machine, looking at the display. The background is dark and appears to be a tunnel or underground setting. A timestamp "2025.8.4" is visible in the bottom right corner of the image.
26	GX-B1328/20-Y-25060	2025. 9. 26	本次共检绝缘靴 12只，12只绝缘靴所检 项目合格。	 A photograph showing a worker in a red helmet and blue uniform sitting at a desk with a computer monitor. The worker is looking at the monitor. Next to the desk is a yellow and black industrial machine. The background is a plain white wall. A timestamp "2025/9/24" is visible in the bottom right corner of the image.

27	GX-B1328/20-Y-25061	2025. 9. 26	本次共检绝缘手套12只，12只绝缘手套所检项目合格。	 地点：中检集团公西安全科技有限公司试验室 2025/9/25
28	GX-B1559/22-Y-25012	2025年9月28日	所检项目合格。	 无锡市天检工程技术有限公司 2025/9/28

29	GX-B1418/23-Y-25001	2025. 9. 26	综合判定：合格。		
30	GX-B1539/22-Y-25054	2025. 9. 30	所检项目合格	 	

31	GX-B1539/22-Y-25055	2025. 9. 30	所检项目合格	 A yellow wheel loader with the number 12 on its side is parked on a dirt surface. Two workers in white protective suits and red hard hats stand in front of the vehicle. A yellow timestamp '2025/9/6' is visible in the bottom right corner of the photo.
32	GX-B1539/22-Y-25056	2025. 9. 30	所检项目合格	 A yellow wheel loader with the number 13 on its side is parked on a dirt surface. Two workers in white protective suits and red hard hats stand in front of the vehicle. A yellow timestamp '2025/9/6' is visible in the bottom right corner of the photo.

33	GX-B1539/22-Y-25057	2025. 9. 30	所检项目合格	  
34	GX-B1539/22-Y-25058	2025. 9. 30	所检项目合格	

35	GX-B1539/22-Y-25059	2025. 9. 30	所检项目合格	 A yellow wheel loader with the number 17 on its side is parked on a gravel surface. Two workers in safety gear stand in front of it. A yellow date stamp '2025/9/6' is in the bottom right corner.
36	GX-B1539/22-Y-25060	2025. 9. 30	所检项目合格	 A yellow wheel loader with the number 18 on its side is parked on a dirt surface in front of a large pile of gravel. Two workers in safety gear stand in front of it. A yellow date stamp '2025/9/6' is in the bottom right corner.