


序号	报告编号	发布日期	结论	影像资料
89	GX-B1328/25-5-25207	2025/11/12	本次共检绝缘手套4只，4只绝缘手套合格。	 2025/11/12
90	GX-B1328/25-5-25208	2025/11/12	本次共检绝缘靴2只，2只绝缘靴合格。	 2025/11/12

91	GX-B1328/25-5-25209	2025/11/12	本次共检验电器1个，1个验电器合格。	 A photograph of a laboratory or workshop setting. In the center, there is a large piece of equipment with yellow metal poles and a circular component. A red safety net is draped around the equipment. In the background, a person wearing a red hard hat and dark clothing is seated at a desk. The floor is made of light-colored tiles. A yellow timestamp '2025/11/12' is overlaid in the bottom right corner of the image.
92	GX-B1328/25-5-25210	2025/11/12	本次共检携带式接地和接地短路装置1套，1套携带式接地和接地短路装置合格。	 A photograph of a laboratory or workshop setting, similar to the one above. It features a large piece of equipment with yellow metal poles and a circular component, surrounded by a red safety net. A person in a red hard hat is visible in the background. The floor is made of light-colored tiles. A yellow timestamp '2025/11/12' is overlaid in the bottom right corner of the image.

93	GX-B1328/25-5-25211	2025/11/14	本次共检绝缘手套8只，8只绝缘手套合格。	 2025/11/14
94	GX-B1328/25-5-25212	2025/11/14	本次共检绝缘靴8只，8只绝缘靴合格。	 2025/11/14

95	GX-B1310/21-5-25275	2025/11/12	符合标准要求。		 A photograph showing a worker in an orange vest and hard hat working on a tall metal structure, possibly a crane or bridge girder. The worker is wearing a safety harness and is positioned between two vertical steel beams. The date '2025/11/08' is visible in the bottom right corner of the photo.	
96	GX-B1310/21-5-25276	2025/11/12	符合标准要求。			

97	GX-B1310/21-5-25277	2025/11/12	符合标准要求。		 A photograph showing a construction worker wearing a red hard hat and a blue shirt, operating a piece of heavy machinery, likely a excavator or crane. The background shows a construction site with blue safety barriers and some greenery. A timestamp "2025/11/08" is visible in the bottom right corner of the photo.  A close-up photograph of mechanical components, possibly a hook or part of a lifting system, showing metal parts and cables. A construction worker in a red hard hat and blue shirt is visible in the background, standing near the machinery. A timestamp "2025/11/08" is visible in the bottom right corner of the photo.	
98	GX-B1310/21-5-25278	2025/11/12	符合标准要求。		 A photograph showing a construction worker wearing a red hard hat and a blue shirt, operating a piece of heavy machinery, likely a excavator or crane. The background shows a construction site with blue safety barriers and some greenery. A timestamp "2025/11/08" is visible in the bottom right corner of the photo.  A close-up photograph of mechanical components, possibly a hook or part of a lifting system, showing metal parts and cables. A construction worker in a red hard hat and blue shirt is visible in the background, standing near the machinery. A timestamp "2025/11/08" is visible in the bottom right corner of the photo.	

99	GX-B1310/21-5-25279	2025/11/12	符合标准要求。		
100	GX-B1310/21-5-25280	2025/11/12	符合标准要求。		

101	GX-B1310/21-5-25281	2025/11/12	符合标准要求。	 A photograph showing two construction workers in safety gear (hard hats and high-visibility vests) working on a large steel structure. One worker is standing and appears to be welding or grinding, while the other is partially visible behind him. The structure consists of thick steel beams and plates. The date '2025/11/08' is printed in yellow at the bottom right of the photo.	
-----	---------------------	------------	---------	--	--